



Date: 7-24-08

FIELD BULLETIN

- Issue:** Occasionally some coins fail to be accepted into the mouth of the coin box inside coin & bill Aurora systems. These coins can slide into the interior of the system and/or get lodged in or under the motherboard.
- Games Affected:** Some coin & bill Auroras built before June 17, 2008. The first six digits of the game's serial number indicate the date of manufacture.
- Symptoms:** Coins are found loose inside the game cabinet. These coins can also slide down to (and under) the motherboard, which can cause functionality issues in the game.
- Solution:** There is a new wide-mouth coin box now available for coin & bill Aurora systems. This coin box (MP0117-01) is available free from your distributor for any coin & bill Aurora made before June 17, 2008. All Auroras made after that date will have the new coin boxes already in place.

If you have any questions, please contact Merit Customer Service and Technical Support by phone at 215-826-1400 or 1-800-523-2760 or by E-mail: TechCenter@meritgames.com.