

Date: 10-22-09

FIELD BULLETIN

Issue: Certain versions of Ion software will not link if there is a wireless "N" router

present, unless they are updated.

Games Affected: Ion systems running 2009 & 2009.5 (from Versions 29.00 to 31.02)

software.

Symptoms: When you perform a wireless scan it will appear that there are no routers to

link to at all, and/or your wireless device will not be able to find a network to

connect to even though there is a functioning router available.

Solution: AMI is issuing a free patch to correct this issue.

<u>For MegaNet-connected games</u>: There is no need to do anything to your machine itself. We have already sent the patch to resolve this issue on your connected machines. Please see the note at the bottom of this bulletin.

If your game is not MegaNet-connected: You can download the patch from our Web site and install it on your game with a USB pen, CD, or DVD. To download the patch, visit www.amientertainment.com > Support > Megatouch Support Center > Software Downloads. This patch will update your game to 2009.5, V31.06. Please see the note below.

IMPORTANT!!

In order for this patch to enable connectivity with your wireless N router, the router must NOT be set to N-only mode. AMI recommends the settings listed below for the following devices (though mixed mode settings should work if your router doesn't have the listed recommended settings):

Wireless Device	Recommended N Router Setting
735	B or B+G mode
705A	G-only mode

To check what kind of wireless device is in your Megatouch system, enter Operator Setup, touch **Diagnostics**, then **System Info**. Look under the heading "Wireless Network" for wireless device information. Please consult your router's instructions for how to switch router modes.

If you have any questions please contact AMI Technical Support by phone at 800-523-2760 or 215-826-1400, or by e-mail at TechCenter@amientertainment.com.