



merit industries, inc.

TECH NOTES

Date: 6-18-97

Re: Megatouch XL countertop games overheating due to obstructed fans and/or vents.

It is important not to place the game manual, or any other documentation, inside of your Megatouch XL game. The material can prevent proper operation of the fans located on the lid of the game. If the fans are not working properly, the game may lock-up and/or damage to the game may result.

It is also important to make sure that the vents, located on the lid and on the bottom of the game, are not obstructed; do not place the game against a wall or on a surface that would prevent air flow through the bottom vents.